


Easy CramBible Lab



HP0-J33

Implementing HP StorageWorks EVA Solutions

**** Single-user License ****

This copy can be only used by yourself for educational purposes

Web: <http://www.crambible.com/>

E-mail: web@crambible.com

Important Note
Please Read Carefully**Study Tips**

This product will provide you questions and answers along with carefully compiled and written by our experts. Try to understand the concepts behind the questions instead of cramming the questions.

Go through the entire document at least twice so that you make sure that you are not missing anything.

Latest Version

We are constantly reviewing our products. New material is added and old material is revised. Free updates are available for 90 days after the purchase. You should check your member zone at CramBible an update 3-4 days before the scheduled exam date.

Here is the procedure to get the latest version:

1. Go to www.CramBible.com
2. Click on Member zone/Log in
3. The latest versions of all purchased products are download from here. Just click the links.

For most updates, it is enough just to print the new questions at the end of the new version, not the whole document.

Feedback

Feedback on specific questions should be send to web@CramBible.com. You should state: Exam number and version, question number, and login ID.

Our experts will answer your mail promptly.

Copyright

Each pdf file contains a unique serial number associated with your particular name and contact information for security purposes. So if we find out that a particular pdf file is being distributed by you, CramBible reserves the right to take legal action against you according to the International Copyright Laws.

THE TOTAL NUMBER OF QUESTIONS IS 65

QUESTION NO: 1 Which feature is unique to the EVA8400 / 11GB cache (per controller) model when compared to other EVA array models?

- A. use of a third cache battery
- B. 400TB addressable storage space
- C. up to 5GB policy memory
- D. maximum of 27 device shelves

Answer: A

QUESTION NO: 2 How does releveling occur after the loss of one disk in a 16-member group containing ten 10GB Vraid1 Vdisks?

- A. The group does not need to relevel.
- B. across 16 disks in the group
- C. across 15 disks in the group
- D. across 14 disks in the group
- E. across 10 disks in the group

Answer: D

QUESTION NO: 3 Which components are mandatory Customer Self Repair (CSR) on an EVA4400, EVA6400 or EVA8400 device shelf? (Select three.)

- A. midplane

- B. power supply
- C. fan
- D. backplane
- E. disk drive
- F. power UID board

Answer: B, C, E

QUESTION NO: 4 for the HP EVA, where do you find error messages, status code values, meanings, and appropriate corrective actions?

- A. product replacement instructions
- B. WEBES System Event Analyzer
- C. product user guide
- D. HP CommandView EVA

Answer: C

QUESTION NO: 5 Which statements are true about mirrorclones? (Select two.)

- A. If the mirrorclone is in a normalized state, you can only detach it.
- B. The redundancy (Vraid) level of a mirrorclone must be the same or higher than the source.
- C. A mirrorclone delta restore may be made when the mirrorclone source is also the source for a DR group.

- D. A detached mirrorclone cannot be reattached to its source.
- E. HP recommends keeping mirrorclones in the same disk group as the source.

Answer: C, D

QUESTION NO: 6 What are functions of the web-based operator control panel of an EVA4400? (Select three.)

- A. view OCP log messages
- B. configure SMI-S credentials
- C. restart a controller
- D. perform disk firmware upgrade
- E. enter WWN to initialize system
- F. perform array firmware upgrade

Answer: A, C, E

QUESTION NO: 7 What must be considered when configuring the Internet Protocol settings of an EVA4400 management module?

- A. The WOCP requires an IPv6 network.
- B. The IP address range is restricted.
- C. A limited set of protocols is supported.
- D. The localhost alias must be disabled.

Answer: B

QUESTION NO: 8 Which statements are true about using thin provisioning in an EVA environment? (Select two.)

- A. Extension of a LUN cannot be automated.
- B. Capacity utilization is increased.
- C. LUN shrink is not always supported for EVA.
- D. Host agents must be installed on servers.
- E. It can be performed within CommandView EVA.

Answer: B, D

QUESTION NO: 9 What are required customer self-repair (replacement) parts in an EVA6400/8400? (Select two.)

- A. controller cache battery
- B. controller cache memory
- C. hard disk drives
- D. disk enclosure fan
- E. Fibre Channel transceivers

Answer: C, D

QUESTION NO: 10 Which service is included in the EVA6400/8400 warranty?

- A. HP Support Plus service
- B. HP EVA Firmware Upgrade service
- C. HP Implementation service